

----- Forwarded message -----
From: Eric Hawkes <eric@ecid.org>
To: Larry Hall <larryh@aquaviron.com>
Cc:
Bcc:
Date: Thu, 12 Jan 2017 09:14:09 -0700
Subject: Re: Lead Copper Consumer Notice & Questions
Hi Larry,

I got a hold of Lynne and forwarded the email over to her and she said she would respond and get it back. I'll forward as soon as I get it.

Thanks,
Eric

On Tue, Jan 10, 2017 at 5:49 PM, Eric Hawkes <eric@ecid.org> wrote:

Hi Larry,

I'll see if I can reach them by phone or I'll go knock on their door tomorrow. Good news on the wells.

Thanks,
Eric

Get [Outlook for iOS](#)

On Tue, Jan 10, 2017 at 4:03 PM -0700, "Larry Hall" <larryh@aquaviron.com> wrote:

Hi Eric,

Did you ever get a response from 142 Young Oak Road? If we can't get them to respond by email we may want to try another approach. I need to follow up on this including repeat samples of both sites. You'll be happy to know I did follow up by testing all of our sources for Lead and Copper just so I can eliminate them as an issue. All the wells were "non Detect" for Lead and Copper with the exception of Freeze Creek Well (WS001) which had levels of; Lead = 0.0007 mg/L (Drinking water Action Level = 0.015 mg/L) and Copper = 0.0011 mg/L (Drinking water Action Level = 1.3 mg/L) so we are well below the required level on a well that is seldom used and "non Detect" on the other three wells.

Please let me know how you think we should proceed with 142 Young Oak Road.

Thank You,

Larry Hall

 AES Email Logo

801.209.6382 (Mobile)

larryh@aquaviron.com